

HABS
ORE
15-MED,
1C-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Medford Service Center, Covered Storage (Building #2300) HABS No. OR-160-C
1319 McAndrews Road
Medford
Jackson County
Oregon

Natalie Brown, Photographer

April 1993

- OR-160-C-1 VIEW OF EAST AND NORTH SIDES OF COVERED STORAGE BUILDING
(BUILDING #2300), FACING SOUTHWEST. VEHICLE "WASH RACK" VISIBLE
ON EAST SIDE.
- OR-160-C-2 VIEW OF SOUTH AND EAST SIDES OF BUILDING #2300 FACING NORTHWEST.
NOTE CURVED KNEE-BRACES ON SUPPORT POSTS.

Note: All photographs are 8" x 10" enlargements from 4" x 5" negatives.